

# Столики. Схемы и типы.

#### Плоские.


Test Anvil M4T P04




Test Anvil M4T P03




Test Anvil M4T P05




Test Anvil M4T P01




Test Anvil M4T P02



## Test Anvil M4T PA2




#### Test Anvil M4T V01



For workpiece diameter 4-10 mm


# V – образной формы

## Test Anvil M4T V01




For workpiece diameter 4-10 mm

## Test Anvil M4T V03




For workpiece diameter 15-55 mm

## Test Anvil M4T V04



For workpiece diameter 22-220 mm

## Test Anvil M4T V02



For workpiece diameter 8-20 mm


# V – образной формы, пониженные

## Test Anvil M4T V11

# 15 3 3 50


For workpiece diameter 4-10 mm

# Test Anvil M4T V12




For workpiece diameter 8-20 mm

# Test Anvil M4T V13




For workpiece diameter 15-55 mm

## Test Anvil M4T V14




For workpiece diameter 22-220 mm

# Наконечники столика




Test Anvil M4T V21

For workpiece diameter 4-10 mm



Test Anvil M4T V22


For workpiece diameter 8-20 mm



Test Anvil M4T V23

For workpiece diameter 15-55 mm


## Наконечники столика для шарикового индентора



Test Anvil M4T K01


For workpiece diameter 4-10 mm

# Столик с пружинным подшипником




Test Anvil M4T S01

## Столики с пружинным зажимом.



Test Anvil M4T A01

For loads 100-700 N



Test Anvil M4T A02

For loads 300-1500 N